

CERTIFICATE OF COMPLIANCE

Certificate Number E506172
Report Reference E506172-20200227
Date 2021-April-05

Issued to: SOCOMEC
1 Rue de Westhouse - B.P. 60010
Benfeld Cedex67235 FR

**This is to certify that
representative samples of**

AUTOMATIC TRANSFER SWITCHES FOR USE IN
EMERGENCY SYSTEMS

See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.


Standard(s) for Safety: UL 1008 : Transfer Switch Equipment
CSA C22.2 NO. 178.1-14 : Transfer Switch Equipment

Additional Information: See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

CERTIFICATE OF COMPLIANCE


Certificate Number E506172
Report Reference E506172-20200227
Date 2021-April-05

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

USL, CNL – Open Type Transfer Switches for use in Emergency Systems:

Type ATyS FT Cat. Nos. 96A02010; 96A12010; 96A03010; 96A13010; 96A04010; 96A02020; 96A12020; 96A03020; 96A13020; 96A04020; 96102010; 96212010; 96303010; 96413010; 96404010; 96102020; 96212020; 96303020; 96413020; 96404020; 96513010; 96504010; 96513020; 96504020.

Type ATyS DT Cat. Nos. 98A03010; 98A13010; 98A04010; 98A03020; 98A13020; 98A04020; 98303010; 98413010; 98404010; 98303020; 98413020; 98404020; 98513010; 98504010; 98513020; 98504020; 96803010; 96803020; 98803010; 98803020.



Bruce Mahrenholz, Director North American Certification Program

UL LLC



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>